



Pins 15-18 keine Durchschleif Funktion!

SDA	P3.1	UCB0SIMO
SCL	P3.2	UCB0SOMI
I/O_1	P1.2	TA1
I/O_2	P1.3	TA2
I/O_3	P4.4	TB1/A13
I/O_4	P4.3	TB0/A12
BUS_1	P3.3	UCB0CLK
BUS_2	P3.0	UCB0STE/A5

TITLE: SPS-Control	
Document Number: www.see-solutions.de	REV: 1.1
Date: 25.12.2009 22:10:25	Sheet: 1/1

Kühlkörper: V 5801B